

Excess Tools Part List & Accessories Declaration Form

Transaction Type : Retirement for Sale / ~~Retirement for Scrap~~ / ~~Intercompany~~ / ~~Inter-Department~~ / ~~Temporary Storage~~
Scrap Reason

FAB : Fab 7
Tool ID : FFSM701
Date : 07-Jun-2019
Module Owner : CVD
**Working Condition/
 Non Working Condition** : Non Working Condition

a. General

Cat	Description
Vendor / Supplier	Frontier Semiconductor (FSM)
Model	128LC2C
Process	Stress Measurement
Vintage (Year of Manufacture)	2004
Serial No.	040330-518
Fixed Asset No.	PCVM0005
Asset Description	FSM 128L-C2C STRESS
Tool Status (Unhooked/Cold shutdown /Warm shutdown/Online)	Cold shutdown
Software Version	NA
CIM	Disconnected

b. Hardware Configuration (Fab)

Cat	Description	Qty / Units	Status,tick if ok[✓]
Main System	Main tool	1	✓
SMIF System	NA	0	NA
Handler System	Wafers transfer robot	1	✓
	Load Port	2	✓
Process Chms	Chamber	0	NA
Others (Pls specify if any)		0	NA

c. Hardware Configuration (Subfab / Auxilliary Units)

Sub Accessories / Auxilliary Units	Qty / Units	Status,tick if ok[✓]

d. Missing/Faulty Parts / Accesories List & Estimated Value

(If NO missing/faulty parts/accesories please indicate NA)

Description	Qty / Units	Estimated USD \$
NA	0	NA
NA	0	NA
NA	0	NA



Tool Photos (Photos must make sense to show all the major parts intact)

FAB : Fab 7
Tool ID : FFSM701
Date : 07-Jun-2019



a. General

Description	Photos
Eqpt ID	FFSM701
Fixed Asset No.	PCVM0005
Vendor / Supplier / Model	Frontier Semiconductor (FSM)
	

b. Hardware Configuration (Fab)

Description	Photos
Main System	
SMIF System Handler System	<p>NA</p> 
Process Chms	

Others(Pls specify if any)



c. Hardware Configuration (Subfab / Auxilliary Units)

Description	Photos

d. Missing Parts [photos showing major missing parts]

Description	Photos

