

Transaction Information

Tool ID	CVD2931U1
Tool Status	Disconnected
Location	Malta, USA
Wafer Size	300 mm
Fab Section	Thin Film
Tool Available Date	2018-09-07

General Product Information

Vendor Supplier	AMAT
Model	PRODUCER GT
Vintage	2014
Serial No	428357-DG-ACHA
Asset Description	NA
Software Version	NA
CIM	NA
Process	BLoKDep

Hardware Configuration (Fab)

System Type	Description	Quantity	Status
Main System			
Main System	UV BLOK Cobalt Chambers	2	
Handler System	-		
Factory Interface	NONE		
Options System			
Others			

Hardware Configuration (Subfab / Auxilliary Units)

Description	Quantity	Status
NONE		

Missing/Faulty Parts / Accesories List

Description	Quantity
ChD water ampoules installed but nothing connected/ plugged in	1
Needs LCF and Chamber D handoffs	1
Edge ring large	1
ChD side1 lift not mounted, harness has pulled wires	1
Missing S1 S2 heater lift mechanism	1
STP-iXR1606 Turbo pump shutting off after few seconds . Turbo having hw problems	1

Description	Quantity
lock nut quartz tube	1
FI lower LL door will not shut when commanded	1
S1 H2O MFC 20 sccm	1
S1 lift controller not attached	1
Missing S1 S2 heater lift driver, lead screw, motor	1
liner LL	1
Edge ring small	1
Missing chamber A/C box cover	1
top plate LL	1
Dump DI water from S1 and S2 DI water container	1
Missing DI water container cover	1
Bucket LL	1
Needs LCF	1
Several cables not connected	1
RPS disconnected	1
tube liner AX7670 APC 300 mm Quartz tube	1
missing door interlock magnet mounting nuts	1
Needs new indexer connector for side 1	1
Needs GUI software work. Comes up only in safe mode. Does not follow commands	1
Gas distribution plate APC	1
Missing S1 S2	1

Description	Quantity
chamber wafer heater	
UPS batteries or battery pack	1

Tool Pictures

General	Eqpt ID
---------	---------











Manufacture Serial

Vendor/Supplier/Model



Additional Configuration Files